

**APPENDIX B  
SUPPORTING DOCUMENTS**

**TAB I**

*Footing repair  
WP 205 +*



**DEH CHO BRIDGE - QUALITY CONTROL MEMO #6**

---

Date: October 28, 2009

Attn: Corey Ross  
Project Manager  
Ruskin Construction Ltd.

Re: Pier #3 and #4 North exposed footing reinforcing steel repairs

---

The exposed footing reinforcing steel in the areas noted below has been repaired as per Ruskin's concrete repair procedure. The repair areas were inspected by both Allnorth quality control and Jivko quality assurances representative prior to concrete placement. Concrete cylinders were cast and break results will be forwarded when received.

Repair areas include:

Pier #3 North footing areas indicated within NCR #3.  
Pier #4 North top approximately 2m<sup>2</sup> on the North West side of the buttress.

Regards,

Steve Pereira  
Quality Control  
Deh Cho Bridge Project